PRINTED: 05/06/2015 FORM APPROVED

05-19-2015

Division of Health Service Regulation					
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01	(X3) DATE SURVEY COMPLETED		
	HAL096022	B. WING	R		
	THE STATE OF THE S		04/24/2015		

NAME OF PROVIDER OR SUPPLIER

STREET ADDRESS, CITY, STATE, ZIP CODE

RENU LIFE EXTENDED

501 FOREST HILL DRIVE GOLDSBORO, NC 27530

-	GOLDSBORO, NC 27530							
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE				
(C 000)	Initial Comments	(C 000)						
	This report is of a Followup Survey done by Bob Getchell on April 24, 2015.							
	Deficiencies were noted which will require a new plan of correction.		CONSTRUCTION SECTION					
{C 133}	Bathrooms-Hand Grips	(C 133)	MAY 1 9 2015					
1.	SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL . ENVIRONMENT		RECEIVED					
	(e) The requirements for bathrooms and toilet rooms are: (6) Hand grips shall be installed at all commodes, tubs and showers used by or accessible to residents;							
	This Rule is not met as evidenced by: 1. Based on observation, the building was not maintained in a safe manner because grab bars are coming loose from the wall. This would effect all residents using the grab bar by exposing them to fall hazards.							
	Findings on 2-17-15;		Maintenance Department has been	6-15-15				
	There are loose grab bars in the back toilet room on the front hall		informed and completed repairs to grab bars in all restrooms.					
(C 189)	Building Equipment Maintained Safe, Operating	(C 189)						
	SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition.							

ivision of Health Service Regulation

ASORATORY DIRECTOR'S OR PROVIDENSUPPLIER REPRESENTATIVE'S SIGNATURE

Administrator

(XII) DATE

TATE FORM

6690

NSZN22

If continuation sheet 1 of 2

PRINTED: 05/08/2015 FORM APPROVED

05-19-2015

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION DENTIFICATION NUMBER: COMPLETED . A. BUILDING: 01 B. WING HAL096022 04/24/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 501 FOREST HILL DRIVE RENU LIFE EXTENDED GOLDSBORO, NC 27530 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX PROVIDER'S PLAN OF CORRECTION (XB) COMPLETE DATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) (C 189) Continued From page 1 (C 189) (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 3. Based on observation, the building was not maintained in a safe manner by not maintaining the fire-resistance rating of building components. This would effect all residents by not containing smoke and fire in the room or smoke compartment of origin. Findings on 2-17-15: Maintenance has been issued a work a. The center corridor wall next to the kitchen has 6-15-15 unprotected penetrations by cable and pipe. order and has completed work on penetrations to both kitchen area as d. There is an unprotected penetration in the well as boiler room wall by conduit. Boller Room wall by condult,

ivision of Health Service Regulation